

# DENT




Table IV, Defect No. 110. Another view of the end seam dent shown in image 32.